U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration Form Approved OMB No. 44-R1387

Required under USDL Safety and Health Regulations for Ship Repairing,

		SECT	ION I			
MANUFACTURER'S NAME Dexter Corporation, Hysol Division	· · · · · · · · · · · · · · · · · · ·	V. Come	EMERGENCY TELEPHON 415/687-4201	E NO.		
ADDRESS (Number, Street, City, State, and ZIP Co 2850 Willow Pass Road (P.O. Box 312), Pit	ode) itsburg	, Californ	ia 94565			
CHEMICAL NAME AND SYNONYMS			TRADE NAME AND SYNONYMS EA 9309 Part B		· · · · · ·	
CHEMICAL FAMILY Aliphatic Amine			FORMULA			
SECTION	111 -	HAZAF	RDOUS INGREDIENTS	,		
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV .(Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)	
PIGMENTS			BASE METAL			
CATALYST			ALLOYS			
VEHICLE	100		METALLIC COATINGS			
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX			
ADDITIVES			OTHERS		`	
OTHERS						
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES					TLV (Units)	
the state of the particle now CER 40 and is classified						
as a Corrosive Liquid. n.o.s. for air shipments.						
as a corrosive grant.						
SEC	CTIO	N III - I	PHYSICAL DATA	<del></del>		
BOILING POINT (°F.) Approxmatel	y	400	SPECIFIC GRAVITY (H2O=1)	_ _	1.0	
VAPOR PRESSURE (mm Hg.)				0 .		
VAPOR DENSITY (AIR=1)		7	BUPBERTURE est		001	
SOLUBILITY IN WATER Almost complete						
APPEARANCE AND ODOR Reddish-o	rang	e liqui	d with ammonical odor			
CCCTION IV	CID	E AND	EXPLOSION HAZARD DATA			
SECTION IV - FIRE AND EXPLOSION HAZARD DATA  FLASH POINT (Method used) > 21.295 TCC   FLAMMABLE LIMITS   Lei   Uei						
-212 F 100						
FOAM, CO	2, W	ater sp	oray, dry chemicals		<u></u>	
SPECIAL FIRE FIGHTING PROCEDURES	lf c	ontaine	ed breathing apparatus should be	ava	i i ab i e	

(Continued on reverse side)

UNUSUAL FIRE AND EXPLOSION HAZARDS

	SECTION V - HEALTH HAZARD DATA
THRESHOLD	IMIT VALUE >5 ppm
DANGER!	venexposure Toxic if absorbed through skin. Causes severe skin and eye burns. May
	cause sensitization and other allergic responses.
EMERGENCY	If contact occurs, wash skin immediately with soap
and wate	. Flush eyes immediately with water for 15 minutes. Get medical
attentio	<u></u>

		SECT	TION VI - REACTIVITY DATA
STABILITY UNSTABLE			CONDITIONS TO AVOID
	STABLE		
INCOMPATABILITY	(Materials to avoid)	. 1	Acids and strong oxidizing agents
HAZARDOUS DECO	MPOSITION PRODU	ICTS	Nitrogen Oxides, CO and/or CO2
HAZARDOUS MAY OCCUI		R	CONDITIONS TO AVOID
POLYMERIZATION	WILL NOT OCCUR		X   Will exotherm when combined with Part A
· · · · · · · · · · · · · · · · · · ·			

STEPS TO BE TAKEN IN C	ASE MATERIA	AL IS REL	EASED OR S	SPILLED	Fluch	awav.	chilled	material	with
			<u> </u>	<del></del>	1 1 (13)	away	Spirieu	ma cer rai	WIGH
large volumes of	water				·			······	· ·
		f	,	1.	* * * * * * * * * * * * * * * * * * * *				
WASTE DISPOSAL METHO	Lar	dfill	or contro	olled	burning	as re	gulated	by all	
governmental agen	cies!		·				•		

	SECTION VIII -	SPECIAL P	ROTECTION IN	FORMATION	
RESPIRATORY PR	OTECTION (Specify type)	Air-suppl	ied mask	• ;	4
VENTILATION	LOCAL EXHAUST	Preferred		SPECIAL	
	MECHANICAL (General)	•		OTHER	
PROTECTIVE GLO	ves Plastic	•	EYE PROTECTION	Goggles	
Face shield	ve equipment i, rubber apron, eye	bath and	safety shower	•	

	SECTION IX - S	SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN	IN HANDLING AND STORIN	Avoid contact with skin or clothing.
OTHER PRECAUTIONS		
•		ANSI Classification 4%5